

Stromnetzgesellschaft Herrenberg mbH & Co. KG



Veröffentlichung der Bewegungsdaten 2012 gem. § 52 Abs.1 EEG

Anlagenschlüssel	Ort	PLZ	BNetzA Vergütungskategorie	ingespeiste Jahresarbeit [kWh]	Vergütung [€]
E10843010000000000000030134400001	Herrenberg	71083	BiK81a1KWK--07	7073	1391,26
E1084301000ZE000000262640RA000001	Herrenberg	71083	WaK231-----09	7701	898,71
E10843010000000000000039005800001	Herrenberg	71083	SgK330-----09	11230	4830,02
E10843010000000000000039058600001	Herrenberg	71083	SgK330-----09	9944	4276,91
E10843010000000000000039071900001	Herrenberg	71083	SgK330-----09	20822	8955,54
E10843010000000000000039104500001	Herrenberg	71083	SgK330-----09	14037	6037,31
E10843010000000000000039221300001	Herrenberg	71083	SgK330-----09	26922	11579,15
E10843010000000000000039270300001	Herrenberg	71083	SgK330-----09	7120	3062,31
E10843010000000000000039318100001	Herrenberg	71083	SgK330-----09	1906	819,77
E108430100000000000000393337300001	Herrenberg	71083	SgK330-----09	28875,36	12419,29
E108430100000000000000393337300001	Herrenberg	71083	SgK331-----09	2910,63	1190,74
E10843010000000000000039388000001	Herrenberg	71083	SgK330-----09	11860	5100,99
E10843010000000000000039435600001	Herrenberg	71083	SgK330-----09	9753	4194,77
E10843010000000000000039447900001	Herrenberg	71083	SgK330-----09	7070	3040,81
E10843010000000000000039510000001	Herrenberg	71083	SgK330-----09	15448	6644,18
E10843010000000000000039534700001	Herrenberg	71083	SgK330-----09	6206	2669,2
E10843010000000000000039665000001	Herrenberg	71083	SgK330-----09	5383	2315,23
E10843010000000000000039678200001	Herrenberg	71083	SgK330-----09	6354	2732,86
E10843010000000000000039723200001	Herrenberg	71083	SgK330-----09	6402	2753,5
E10843010000000000000039842800001	Herrenberg	71083	SgK330-----09	9365	4027,89
E10843010000000000000039966600001	Herrenberg	71083	SgK330-----09	9283	3992,62
E10843010000000000000040065800001	Herrenberg	71083	SgK330-----09	10271	4417,55
E10843010000000000000040077600001	Herrenberg	71083	SgK330-----09	4412	1897,6
E10843010000000000000040186200001	Herrenberg	71083	SgK330-----09	14977	6441,61
E10843010000000000000040251700001	Herrenberg	71083	SgK330-----09	13023	5601,19
E10843010000000000000040392900001	Herrenberg	71083	SgK330-----09	13630	5862,26
E10843010000000000000040416600001	Herrenberg	71083	SgK330-----09	7185	3090,27
E10843010000000000000042839900001	Herrenberg	71083	SgK330-----10	3691	1444,66
E10843010000000000000042840100001	Herrenberg	71083	SgK330-----09	24840	10683,68
E10843010000000000000043178700001	Herrenberg	71083	SgK330-----10	5246	2053,28
E10843010000000000000043206800001	Herrenberg	71083	SgK330-----10	8632	3378,56
E10843010000000000000043353400001	Herrenberg	71083	SgK330-----10	8346	3266,62
E10843010000000000000043366700001	Herrenberg	71083	SgK330-----10	7688	3009,08
E10843010000000000000043366800001	Herrenberg	71083	SgK330-----10	8793	3441,58
E10843010000000000000043436200001	Herrenberg	71083	SgK330-----10	7030	2751,54
E10843010000000000000038641000001	Herrenberg	71083	SgK3342----09	-2110	-379,8
E10843010000000000000038917700001	Herrenberg	71083	SgK330-----09	4706	2024,05
E10843010000000000000039000800001	Herrenberg	71083	SgK330-----09	8475	3645,1
E10843010000000000000039000800001	Herrenberg	71083	SgK3341----09	1596	686,44
E10843010000000000000039000800001	Herrenberg	71083	SgK3342----09	-1596	-287,28
E10843010000000000000039001000001	Herrenberg	71083	SgK330-----09	5327	2291,14
E10843010000000000000039001000001	Herrenberg	71083	SgK3341----09	1339	575,9
E10843010000000000000039001000001	Herrenberg	71083	SgK3342----09	-1339	-241,02

E108430100000000000000039005700001	Herrenberg	71083	SgK330-----09	6307	2712,64
E108430100000000000000040424700001	Herrenberg	71083	SgK330-----09	37719	16222,94
E108430100000000000000040436400001	Herrenberg	71083	SgK330-----09	2626	1129,44
E108430100000000000000040455000001	Herrenberg	71083	SgK330-----09	35898	15439,73
E108430100000000000000040524500001	Herrenberg	71083	SgK330-----09	13404	5765,06
E108430100000000000000040757100001	Herrenberg	71083	SgK330-----09	19178	8248,46
E108430100000000000000040779300001	Herrenberg	71083	SgK330-----09	6725	2892,42
E108430100000000000000040856500001	Herrenberg	71083	SgK330-----09	7781	3346,61
E108430100000000000000040884700001	Herrenberg	71083	SgK330-----09	12464	5360,77
E108430100000000000000040903700001	Herrenberg	71083	SgK330-----09	9173	3945,31
E108430100000000000000040943300001	Herrenberg	71083	SgK330-----09	27597	11869,47
E108430100000000000000040974100001	Herrenberg	71083	SgK330-----09	7063	3037,8
E108430100000000000000041035100001	Herrenberg	71083	SgK330-----09	4325	1860,18
E108430100000000000000041041100001	Herrenberg	71083	SgK330-----09	8442	3630,9
E108430100000000000000041171800001	Herrenberg	71083	SgK330-----09	11656	5013,25
E108430100000000000000041187900001	Herrenberg	71083	SgK330-----10	9457	3701,47
E108430100000000000000041351500001	Herrenberg	71083	SgK330-----09	10070	4331,11
E108430100000000000000041384900001	Herrenberg	71083	SgK330-----09	6204	2668,34
E108430100000000000000041432000001	Herrenberg	71083	SgK330-----09	12258,74	5272,49
E108430100000000000000041432000001	Herrenberg	71083	SgK331-----09	1149,25	470,16
E108430100000000000000041516300001	Herrenberg	71083	SgK330-----09	34407,88	14798,83
E108430100000000000000041516300001	Herrenberg	71083	SgK331-----09	3693,11	1510,85
E108430100000000000000041525200001	Herrenberg	71083	SgK330-----09	7367	3168,55
E108430100000000000000041580500001	Herrenberg	71083	SgK330-----09	18250	7849,33
E108430100000000000000041670000001	Herrenberg	71083	SgK330-----09	33969,2	14610,15
E108430100000000000000041670000001	Herrenberg	71083	SgK331-----09	3532,79	1445,27
E108430100000000000000041755900001	Herrenberg	71083	SgK330-----09	6501	2796,08
E108430100000000000000041901700001	Herrenberg	71083	SgK330-----09	5224	2246,84
E108430100000000000000042128200001	Herrenberg	71083	SgK330-----09	24230	10421,32
E108430100000000000000042143400001	Herrenberg	71083	SgK330-----09	11697	5030,88
E108430100000000000000042207400001	Herrenberg	71083	SgK330-----09	12681	5454,1
E108430100000000000000042433300001	Herrenberg	71083	SgK330-----09	9007	3873,91
E108430100000000000000042508800001	Herrenberg	71083	SgK330-----09	7453	3205,54
E108430100000000000000042768900001	Herrenberg	71083	SgK330-----10	9856	3857,64
E108430100000000000000042817000001	Herrenberg	71083	SgK330-----09	9956	4282,08
E108430100000000000000043494700001	Herrenberg	71083	SgK330-----10	6857	2683,83
E108430100000000000000043555100001	Herrenberg	71083	SgK330-----10	4819	1886,16
E108430100000000000000043555100001	Herrenberg	71083	SgK3341-----10	1564	612,15
E108430100000000000000043555100001	Herrenberg	71083	SgK3342-----10	-1564	-256,18
E108430100000000000000043629900001	Herrenberg	71083	SgK330-----10	8225	3219,27
E108430100000000000000043666700001	Herrenberg	71083	SgK330-----10	10848	4245,91
E108430100000000000000043696100001	Herrenberg	71083	SgK330-----10	7295	2855,26
E108430100000000000000043811600001	Herrenberg	71083	SgK330-----10	9535	3732
E108430100000000000000043923200001	Herrenberg	71083	SgK330-----10	9617	3764,09
E108430100000000000000043930200001	Herrenberg	71083	SgK330-----10	15993	6259,66
E108430100000000000000044119800001	Herrenberg	71083	SgK330-----10	12404	4854,93
E108430100000000000000044141400001	Herrenberg	71083	SgK330-----10	8408	3290,89
E108430100000000000000044159900001	Herrenberg	71083	SgK330-----10	8523	3335,9
E108430100000000000000044159900001	Herrenberg	71083	SgK3341-----10	1377	538,96
E108430100000000000000044159900001	Herrenberg	71083	SgK3342-----10	-1377	-225,55
E108430100000000000000044207000001	Herrenberg	71083	SgK330-----10	6728	2633,34

E108430100000000000000044207000001	Herrenberg	71083	SgK3341-----10	1607	628,98
E108430100000000000000044207000001	Herrenberg	71083	SgK3342-----10	-1607	-263,23
E108430100000000000000044216700001	Herrenberg	71083	SgK330-----10	11654	4561,38
E108430100000000000000044228100001	Herrenberg	71083	SgK330-----10	11257	4405,99
E108430100000000000000044239900001	Herrenberg	71083	SgK330-----10	8826	3454,5
E108430100000000000000044281100001	Herrenberg	71083	SgK330-----10	19776	7740,33
E108430100000000000000044281100001	Herrenberg	71083	SgK3341-----10	1574	616,06
E108430100000000000000044281100001	Herrenberg	71083	SgK3342-----10	-1574	-257,82
E108430100000000000000044316300001	Herrenberg	71083	SgK330-----10	7933	3104,98
E108430100000000000000044341700001	Herrenberg	71083	SgK330-----10	12999	5087,81
E108430100000000000000044353300001	Herrenberg	71083	SgK330-----10	7891	3088,54
E108430100000000000000044389100001	Herrenberg	71083	SgK330---Jul10	30422,11	10358,73
E108430100000000000000044389100001	Herrenberg	71083	SgK331---Jul10	1216,88	394,15
E108430100000000000000044396100001	Herrenberg	71083	SgK330-----10	10462	4094,83
E108430100000000000000044396100001	Herrenberg	71083	SgK3341-----10	2035	796,5
E108430100000000000000044396100001	Herrenberg	71083	SgK3342-----10	-2035	-333,33
E108430100000000000000044435100001	Herrenberg	71083	SgK330-----10	4426	1732,34
E108430100000000000000044443500001	Herrenberg	71083	SgK330-----10	4817	1885,37
E108430100000000000000044561800001	Herrenberg	71083	SgK330-----10	8181	3202,04
E108430100000000000000044575800001	Herrenberg	71083	SgK330-----10	10800	4227,12
E108430100000000000000044745500001	Herrenberg	71083	SgK330-----10	32811,45	12842,4
E108430100000000000000044745500001	Herrenberg	71083	SgK331-----10	61685,54	22965,53
E108430100000000000000044750900001	Herrenberg	71083	SgK330-----10	7343	2874,05
E108430100000000000000044782800001	Herrenberg	71083	SgK330-----10	5143	2012,97
E108430100000000000000044797800001	Herrenberg	71083	SgK330-----10	8863	3468,98
E108430100000000000000044814400001	Herrenberg	71083	SgK330-----10	2221	869,3
E108430100000000000000044814400001	Herrenberg	71083	SgK3341-----10	1496	585,53
E108430100000000000000044814400001	Herrenberg	71083	SgK3342-----10	-1496	-245,04
E108430100000000000000044832200001	Herrenberg	71083	SgK330-----10	13112	5132,04
E108430100000000000000044836600001	Herrenberg	71083	SgK330-----10	18084	7078,08
E108430100000000000000044920300001	Herrenberg	71083	SgK330-----10	14966	5857,69
E108430100000000000000044920400001	Herrenberg	71083	SgK330-----10	5391	2110,04
E108430100000000000000044920400001	Herrenberg	71083	SgK3341-----10	908	355,39
E108430100000000000000044920400001	Herrenberg	71083	SgK3342-----10	-908	-148,73
E108430100000000000000044952100001	Herrenberg	71083	SgK330-----10	10908	4269,39
E108430100000000000000044965200001	Herrenberg	71083	SgK330-----10	9654	3778,58
E108430100000000000000045086000001	Herrenberg	71083	SgK330-----10	17791	6963,4
E108430100000000000000045086000001	Herrenberg	71083	SgK3341-----10	1280	500,99
E108430100000000000000045086000001	Herrenberg	71083	SgK3342-----10	-1280	-209,66
E108430100000000000000045108100001	Herrenberg	71083	SgK330-----10	26938	10543,53
E108430100000000000000045111600001	Herrenberg	71083	SgK330-----10	9455	3700,69
E108430100000000000000045111600001	Herrenberg	71083	SgK3341-----10	2387	934,27
E108430100000000000000045111600001	Herrenberg	71083	SgK3342-----10	-2387	-390,99
E108430100000000000000045144400001	Herrenberg	71083	SgK330-----10	30872,02	12083,31
E108430100000000000000045144400001	Herrenberg	71083	SgK331-----10	61280,97	22814,9
E108430100000000000000045161900001	Herrenberg	71083	SgK330-----10	11191	4380,16
E108430100000000000000045255900001	Herrenberg	71083	SgK330-----10	10794	4224,77
E108430100000000000000045312400001	Herrenberg	71083	SgK330-----10	8259	3232,57
E108430100000000000000045327800001	Herrenberg	71083	SgK330-----10	11044	4322,62
E108430100000000000000045445200001	Herrenberg	71083	SgK330-----10	30226,85	11830,79
E108430100000000000000045445200001	Herrenberg	71083	SgK331-----10	15476,14	5761,78

E108430100000000000000045456100001	Herrenberg	71083	SgK330-----10	6037	2362,88
E108430100000000000000045466000001	Herrenberg	71083	SgK330-----10	6098	2386,76
E108430100000000000000045539100001	Herrenberg	71083	SgK330-----10	3898	1525,68
E108430100000000000000045554300001	Herrenberg	71083	SgK330-----10	2279	892
E108430100000000000000045554300001	Herrenberg	71083	SgK3341-----10	7014	2745,28
E108430100000000000000045554300001	Herrenberg	71083	SgK3342-----10	-7014	-1148,89
E108430100000000000000045567600001	Herrenberg	71083	SgK330-----10	4313	1688,11
E108430100000000000000045627300001	Herrenberg	71083	SgK330-----10	11086	4339,06
E108430100000000000000045656700001	Herrenberg	71083	SgK330-----10	7059	2762,89
E108430100000000000000045662400001	Herrenberg	71083	SgK330-----10	4480	1753,47
E108430100000000000000045743600001	Herrenberg	71083	SgK330-----10	2765	1082,22
E108430100000000000000045743600001	Herrenberg	71083	SgK3341-----10	1335	522,52
E108430100000000000000045743600001	Herrenberg	71083	SgK3342-----10	-1335	-218,67
E108430100000000000000045765300001	Herrenberg	71083	SgK330-----10	18609	7283,56
E108430100000000000000045838400001	Herrenberg	71083	SgK330-----10	5082	1989,09
E108430100000000000000045881100001	Herrenberg	71083	SgK330-----10	3456	1352,68
E108430100000000000000045881100001	Herrenberg	71083	SgK3341-----10	829	324,47
E108430100000000000000045881100001	Herrenberg	71083	SgK3342-----10	-829	-135,79
E108430100000000000000045962100001	Herrenberg	71083	SgK330-----10	15101	5910,53
E108430100000000000000045961100001	Herrenberg	71083	SgK330-----10	9583	3750,79
E108430100000000000000045967500001	Herrenberg	71083	SgK330-----10	29490	11542,39
E108430100000000000000045973700001	Herrenberg	71083	SgK330-----10	11929	4669,01
E108430100000000000000045985100001	Herrenberg	71083	SgK330-----10	3460	1354,24
E108430100000000000000045985100001	Herrenberg	71083	SgK3341-----10	1938	758,53
E108430100000000000000045985100001	Herrenberg	71083	SgK3342-----10	-1938	-317,44
E108430100000000000000046022900001	Herrenberg	71083	SgK330-----10	5358	2097,12
E108430100000000000000046090600001	Herrenberg	71083	SgK330---Jul10	5652	1924,51
E108430100000000000000046128200001	Herrenberg	71083	SgK330---Jul10	15056	5126,57
E108430100000000000000046128200001	Herrenberg	71083	SgK33410-Jul10	994	338,46
E108430100000000000000046128200001	Herrenberg	71083	SgK33420-Jul10	-994	-162,82
E108430100000000000000046139200001	Herrenberg	71083	SgK330-----10	8291	3245,1
E108430100000000000000046275600001	Herrenberg	71083	SgK330-----10	4542	1777,74
E108430100000000000000046276400001	Herrenberg	71083	SgK330-----10	12344	4831,44
E108430100000000000000046702800001	Herrenberg	71083	SgK330-----10	13344	5222,84
E108430100000000000000046853300001	Herrenberg	71083	SgK330---Jul10	2478	843,76
E108430100000000000000046853300001	Herrenberg	71083	SgK33410-Jul10	2946	1003,11
E108430100000000000000046853300001	Herrenberg	71083	SgK33420-Jul10	-1627	-266,5
E108430100000000000000046853300001	Herrenberg	71083	SgK33430-Jul10	-1319	-158,28
E108430100000000000000046879700001	Herrenberg	71083	SgK330-----10	10451,66	4090,78
E108430100000000000000046879700001	Herrenberg	71083	SgK331-----10	10,33	3,85
E108430100000000000000047175600001	Herrenberg	71083	SgK330---Jul10	7341	2499,61
E108430100000000000000047175600001	Herrenberg	71083	SgK33410-Jul10	1515	515,86
E108430100000000000000047175600001	Herrenberg	71083	SgK33420-Jul10	-1515	-248,16
E108430100000000000000047287100001	Herrenberg	71083	SgK330-----10	24411	9554,47
E108430100000000000000047375300001	Herrenberg	71083	SgK330---Jul10	8958	3050,2
E108430100000000000000047498800001	Herrenberg	71083	SgK330---Jul10	12172	4144,57
E108430100000000000000047538300001	Herrenberg	71083	SgK330---Jul10	5679	1933,7
E108430100000000000000047538300001	Herrenberg	71083	SgK33410-Jul10	1035	352,42
E108430100000000000000047538300001	Herrenberg	71083	SgK33420-Jul10	-1035	-169,53
E108430100000000000000047606600001	Herrenberg	71083	SgK330---Jul10	2881	980,98
E108430100000000000000047606600001	Herrenberg	71083	SgK33410-Jul10	1418	482,83

E108430100000000000000047606600001	Herrenberg	71083	SgK33420-Jul10	-1290	-211,3
E108430100000000000000047606600001	Herrenberg	71083	SgK33430-Jul10	-128	-15,36
E108430100000000000000047607000001	Herrenberg	71083	SgK330---Jul10	7341	2499,61
E108430100000000000000047607000001	Herrenberg	71083	SgK33410-Jul10	1954	665,34
E108430100000000000000047607000001	Herrenberg	71083	SgK33420-Jul10	-1954	-320,07
E108430100000000000000047762800001	Herrenberg	71083	SgK330---Jul10	6153	2095,1
E108430100000000000000047861500001	Herrenberg	71083	SgK330---Okt10	14732	4865,98
E108430100000000000000047866000001	Herrenberg	71083	SgK330---Okt10	4088	1350,27
E108430100000000000000047950900001	Herrenberg	71083	SgK330---Jul10	8966	3052,92
E108430100000000000000048290600001	Herrenberg	71083	SgK330---Jul10	3094	1053,51
E108430100000000000000048353900001	Herrenberg	71083	SgK330---Jul10	10983	3739,71
E108430100000000000000048517900001	Herrenberg	71083	SgK330---Okt10	26758	8838,17
E108430100000000000000048517900001	Herrenberg	71083	SgK33410-Okt10	2325	767,95
E108430100000000000000048517900001	Herrenberg	71083	SgK33420-Okt10	-2325	-380,84
E108430100000000000000048539800001	Herrenberg	71083	SgK330---Okt10	4772	1576,19
E108430100000000000000048539800001	Herrenberg	71083	SgK33410-Okt10	710	234,51
E108430100000000000000048539800001	Herrenberg	71083	SgK33420-Okt10	-710	-116,3
E108430100000000000000048582200001	Herrenberg	71083	SgK330---Jul10	26403	8990,22
E108430100000000000000048586200001	Herrenberg	71083	SgK330---Jul10	12310	4191,56
E108430100000000000000049052100001	Herrenberg	71083	SgK330---Okt10	1974	652,01
E108430100000000000000049052100001	Herrenberg	71083	SgK33410-Okt10	1082	357,39
E108430100000000000000049052100001	Herrenberg	71083	SgK33420-Okt10	-917	-150,2
E108430100000000000000049052100001	Herrenberg	71083	SgK33430-Okt10	-165	-19,8
E108430100000000000000049068800001	Herrenberg	71083	SgK330---Okt10	10946	3615,46
E108430100000000000000049112900001	Herrenberg	71083	SgK330-----10	7965	3117,5
E108430100000000000000049119300001	Herrenberg	71083	SgK330---Okt10	6068	2004,26
E108430100000000000000049119300001	Herrenberg	71083	SgK33410-Okt10	2043	674,8
E108430100000000000000049119300001	Herrenberg	71083	SgK33420-Okt10	-2043	-334,64
E108430100000000000000049320500001	Herrenberg	71083	SgK330-----11	7723	2219,59
E108430100000000000000049585300001	Herrenberg	71083	SgK330---Okt10	8249	2724,64
E108430100000000000000050151500001	Herrenberg	71083	SgK330-----11	2356	677,11
E108430100000000000000050151500001	Herrenberg	71083	SgK33410----11	1134	325,91
E108430100000000000000050151500001	Herrenberg	71083	SgK33420----11	-1047	-171,5
E108430100000000000000050151500001	Herrenberg	71083	SgK33430----11	-87	-10,44
E108430100000000000000050158300001	Herrenberg	71083	SgK330---Okt10	6656	2198,48
E108430100000000000000050181600001	Herrenberg	71083	SgK330-----11	3784	1087,52
E108430100000000000000050181600001	Herrenberg	71083	SgK33410----11	1351	388,28
E108430100000000000000050181600001	Herrenberg	71083	SgK33420----11	-1351	-221,29
E108430100000000000000050275300001	Herrenberg	71083	SgK330-----11	15777	4534,31
E108430100000000000000050357900001	Herrenberg	71083	SgK330---Okt10	4288	1416,33
E108430100000000000000050357900001	Herrenberg	71083	SgK33410-Okt10	1708	564,15
E108430100000000000000050357900001	Herrenberg	71083	SgK33420-Okt10	-1708	-279,77
E175940100000000000000050552300001	Herrenberg	71083	SgK330-----11	4354	1251,34
E175940100000000000000050552300001	Herrenberg	71083	SgK33410----11	1913	549,79
E175940100000000000000050552300001	Herrenberg	71083	SgK33420----11	-1880	-307,94
E175940100000000000000050552300001	Herrenberg	71083	SgK33430----11	-33	-3,96
E108430100000000000000051368800001	Herrenberg	71083	SgK330---Okt10	2667	880,91
E108430100000000000000051368800001	Herrenberg	71083	SgK33410-Okt10	2263	747,47
E108430100000000000000051368800001	Herrenberg	71083	SgK33420-Okt10	-1479	-242,26
E108430100000000000000051368800001	Herrenberg	71083	SgK33430-Okt10	-784	-94,08
E175940100000000000000051828600001	Herrenberg	71083	SgK330-----11	1179	338,84

E17594010000000000000051828600001	Herrenberg	71083	SgK33410----11	1528	439,15
E17594010000000000000051828600001	Herrenberg	71083	SgK33420----11	-812	-133,01
E17594010000000000000051828600001	Herrenberg	71083	SgK33430----11	-716	-85,92
E17594010000000000000051981900001	Herrenberg	71083	SgK330-----11	8288	2381,97
E17594010000000000000051981900001	Herrenberg	71083	SgK33410----11	1528	439,15
E17594010000000000000051981900001	Herrenberg	71083	SgK33420----11	-1528	-250,29
E17594010000000000000052041000001	Herrenberg	71083	SgK330-----11	5507	1582,71
E17594010000000000000052041000001	Herrenberg	71083	SgK33410----11	1238	355,8
E17594010000000000000052041000001	Herrenberg	71083	SgK33420----11	-1238	-202,78
E17594010000000000000052208500001	Herrenberg	71083	SgK331-----11	48451	13241,67
E17594010000000000000052281200001	Herrenberg	71083	SgK330-----11	5004	1438,15
E17594010000000000000052281200001	Herrenberg	71083	SgK33410----11	1421	408,4
E17594010000000000000052281200001	Herrenberg	71083	SgK33420----11	-1421	-232,76
E17594010000000000000052460700001	Herrenberg	71083	SgK330-----11	6605	1898,28
E17594010000000000000052460700001	Herrenberg	71083	SgK33410----11	1733	498,06
E17594010000000000000052460700001	Herrenberg	71083	SgK33420----11	-1733	-283,87
E17594010000000000000052539600001	Herrenberg	71083	SgK330-----11	12606	3622,96
E17594010000000000000052539600001	Herrenberg	71083	SgK33410----11	1632	469,04
E17594010000000000000052539600001	Herrenberg	71083	SgK33420----11	-1632	-267,32
E17594010000000000000052586800001	Herrenberg	71083	SgK330-----11	3105	892,38
E17594010000000000000052586800001	Herrenberg	71083	SgK33410----11	1178	338,56
E17594010000000000000052586800001	Herrenberg	71083	SgK33420----11	-1178	-192,96
E17594010000000000000052602800001	Herrenberg	71083	SgK330-----11	13602	3909,21
E17594010000000000000052662300001	Herrenberg	71083	SgK333-----11	608813	131260,09
E17594010000000000000052665400001	Herrenberg	71083	SgK330-----11	33132,8	9522,35
E17594010000000000000052665400001	Herrenberg	71083	SgK331-----11	77309,88	21128,79
E17594010000000000000052665400001	Herrenberg	71083	SgK332-----11	993984,25	257044,34
E17594010000000000000052665400001	Herrenberg	71083	SgK333-----11	517181,05	111504,23
E17594010000000000000052715900001	Herrenberg	71083	SgK330-----11	28933,07	8315,37
E17594010000000000000052715900001	Herrenberg	71083	SgK331-----11	5940,92	1623,65
E17594010000000000000052791900001	Herrenberg	71083	SgK330-----11	33358,97	9587,39
E17594010000000000000052791900001	Herrenberg	71083	SgK331-----11	27510,02	7518,48
E17594010000000000000052830400001	Herrenberg	71083	SgK330-----11	10002	2874,57
E17594010000000000000052830400001	Herrenberg	71083	SgK33410----11	1923	552,67
E17594010000000000000052830400001	Herrenberg	71083	SgK33420----11	-1923	-314,99
E17594010000000000000052880800001	Herrenberg	71083	SgK330-----11	5826	1674,39
E17594010000000000000052880800001	Herrenberg	71083	SgK33410----11	1054	302,92
E17594010000000000000052880800001	Herrenberg	71083	SgK33420----11	-1054	-172,65
E17594010000000000000052881200001	Herrenberg	71083	SgK330-----11	6226	1789,35
E17594010000000000000052881200001	Herrenberg	71083	SgK33410----11	760	218,42
E17594010000000000000052881200001	Herrenberg	71083	SgK33420----11	-760	-124,49
E17594010000000000000052925600001	Herrenberg	71083	SgK330-----11	6110	1756,01
E17594010000000000000052925600001	Herrenberg	71083	SgK33410----11	2355	676,83
E17594010000000000000052925600001	Herrenberg	71083	SgK33420----11	-2355	-385,75
E17594010000000000000052909700001	Herrenberg	71083	SgK330-----11	9751	2802,44
E17594010000000000000052909700001	Herrenberg	71083	SgK33410----11	2390	686,89
E17594010000000000000052909700001	Herrenberg	71083	SgK33420----11	-2390	-391,48
E17594010000000000000053043300001	Herrenberg	71083	SgK330-----11	6681	1920,12
E17594010000000000000053043300001	Herrenberg	71083	SgK33410----11	1177	338,27
E17594010000000000000053043300001	Herrenberg	71083	SgK33420----11	-1177	-192,79
E17594010000000000000053074300001	Herrenberg	71083	SgK330-----11	3970	1140,98

E17594010000000000000053074300001	Herrenberg	71083	SgK33410----11	1486	427,08
E17594010000000000000053074300001	Herrenberg	71083	SgK33420----11	-1486	-243,41
E17594010000000000000053205400001	Herrenberg	71083	SgK330-----11	4653	1337,27
E17594010000000000000053205400001	Herrenberg	71083	SgK33410----11	1143	328,5
E17594010000000000000053205400001	Herrenberg	71083	SgK33420----11	-1143	-187,22
E17594010000000000000053268800001	Herrenberg	71083	SgK330-----11	4569	1313,13
E17594010000000000000053268800001	Herrenberg	71083	SgK33410----11	2224	639,18
E17594010000000000000053268800001	Herrenberg	71083	SgK33420----11	-2038	-333,82
E17594010000000000000053268800001	Herrenberg	71083	SgK33430----11	-186	-22,32
E17594010000000000000053273900001	Herrenberg	71083	SgK330-----11	2980	856,45
E17594010000000000000053273900001	Herrenberg	71083	SgK33410----11	1686	484,56
E17594010000000000000053273900001	Herrenberg	71083	SgK33420----11	-1400	-229,32
E17594010000000000000053273900001	Herrenberg	71083	SgK33430----11	-286	-34,32
E17594010000000000000053453800001	Herrenberg	71083	SgK330-----11	10060,3	2891,33
E17594010000000000000053453800001	Herrenberg	71083	SgK331-----11	5727,7	1565,38
E17594010000000000000053453800001	Herrenberg	71083	SgK33410----11	22447,1	6451,3
E17594010000000000000053453800001	Herrenberg	71083	SgK33411----11	12779,9	3492,75
E17594010000000000000053453800001	Herrenberg	71083	SgK33420----11	-9752,5	-1597,46
E17594010000000000000053453800001	Herrenberg	71083	SgK33421----11	-5552,5	-909,5
E17594010000000000000053453800001	Herrenberg	71083	SgK33430----11	-12694,6	-1523,35
E17594010000000000000053453800001	Herrenberg	71083	SgK33431----11	-7227,4	-867,29
E17594010000000000000053516500001	Herrenberg	71083	SgK330-----11	10035	2884,06
E17594010000000000000053543000001	Herrenberg	71083	SgK330-----11	8581	2466,18
E17594010000000000000053543000001	Herrenberg	71083	SgK33410----11	1463	420,47
E17594010000000000000053543000001	Herrenberg	71083	SgK33420----11	-1463	-239,64
E17594010000000000000053552500001	Herrenberg	71083	SgK330-----11	13591	3906,05
E17594010000000000000053552500001	Herrenberg	71083	SgK33410----11	1880	540,31
E17594010000000000000053552500001	Herrenberg	71083	SgK33420----11	-1880	-307,94
E17594010000000000000053592100001	Herrenberg	71083	SgK330-----11	15282	4392,05
E17594010000000000000053592100001	Herrenberg	71083	SgK33410----11	1720	494,33
E17594010000000000000053592100001	Herrenberg	71083	SgK33420----11	-1720	-281,74
E17594010000000000000053667800001	Herrenberg	71083	SgK330-----11	3943	1133,22
E17594010000000000000053667800001	Herrenberg	71083	SgK33410----11	2201	632,57
E17594010000000000000053667800001	Herrenberg	71083	SgK33420----11	-1843	-301,88
E17594010000000000000053667800001	Herrenberg	71083	SgK33430----11	-358	-42,96
E17594010000000000000053668200001	Herrenberg	71083	SgK330-----11	5218	1499,65
E17594010000000000000053668200001	Herrenberg	71083	SgK33410----11	1129	324,47
E17594010000000000000053668200001	Herrenberg	71083	SgK33420----11	-1129	-184,93
E17594010000000000000053747700001	Herrenberg	71083	SgK330-----11	7136	2050,89
E17594010000000000000053758500001	Herrenberg	71083	SgK330-----11	4850	1393,89
E17594010000000000000053836000001	Herrenberg	71083	SgK330-----11	7414	2130,78
E17594010000000000000053836000001	Herrenberg	71083	SgK33410----11	2196	631,13
E17594010000000000000053836000001	Herrenberg	71083	SgK33420----11	-2196	-359,7
E17594010000000000000053879500001	Herrenberg	71083	SgK330-----11	2098	602,97
E17594010000000000000053879500001	Herrenberg	71083	SgK33410----11	957	275,05
E17594010000000000000053879500001	Herrenberg	71083	SgK33420----11	-917	-150,2
E17594010000000000000053879500001	Herrenberg	71083	SgK33430----11	-40	-4,8
E17594010000000000000053959200001	Herrenberg	71083	SgK330-----11	7043	2024,16
E17594010000000000000053959200001	Herrenberg	71083	SgK33410----11	2934	843,23
E17594010000000000000053959200001	Herrenberg	71083	SgK33420----11	-2934	-480,59
E17594010000000000000054092000001	Herrenberg	71083	SgK330-----11	14785	4249,21

E17594010000000000000054552600001	Herrenberg	71083	SgK330-----11	8579	2465,6
E17594010000000000000054736300001	Herrenberg	71083	SgK330-----11	5147	1479,25
E17594010000000000000054736300001	Herrenberg	71083	SgK33410----11	3149	905,02
E17594010000000000000054736300001	Herrenberg	71083	SgK33420----11	-2489	-407,7
E17594010000000000000054736300001	Herrenberg	71083	SgK33430----11	-660	-79,2
E17594010000000000000054786900001	Herrenberg	71083	SgK330-----11	11268	3238,42
E17594010000000000000054786900001	Herrenberg	71083	SgK33410----11	1492	428,8
E17594010000000000000054786900001	Herrenberg	71083	SgK33420----11	-1492	-244,39
E17594010000000000000054921000001	Herrenberg	71083	SgK330-----11	4550	1307,67
E17594010000000000000054921000001	Herrenberg	71083	SgK33410----11	1453	417,59
E17594010000000000000054921000001	Herrenberg	71083	SgK33420----11	-1453	-238
E17594010000000000000055126600001	Herrenberg	71083	SgK330-----11	8101	2328,23
E17594010000000000000055220000001	Herrenberg	71083	SgK330-----11	8727	2508,14
E17594010000000000000055220000001	Herrenberg	71083	SgK33410----11	2409	692,35
E17594010000000000000055220000001	Herrenberg	71083	SgK33420----11	-2409	-394,59
E17594010000000000000055256000001	Herrenberg	71083	SgK330-----11	2916	838,06
E17594010000000000000055256000001	Herrenberg	71083	SgK33410----11	810	232,79
E17594010000000000000055256000001	Herrenberg	71083	SgK33420----11	-810	-132,68
E17594010000000000000055285400001	Herrenberg	71083	SgK330-----11	3890	1117,99
E17594010000000000000055285400001	Herrenberg	71083	SgK33410----11	1666	478,81
E17594010000000000000055285400001	Herrenberg	71083	SgK33420----11	-1666	-272,89
E17594010000000000000055360200001	Herrenberg	71083	SgK330-----11	9801	2816,81
E17594010000000000000055360200001	Herrenberg	71083	SgK33410----11	2074	596,07
E17594010000000000000055360200001	Herrenberg	71083	SgK33420----11	-2074	-339,72
E17594010000000000000055409300001	Herrenberg	71083	SgK330-----11	15940	4581,16
E17594010000000000000055473200001	Herrenberg	71083	SgK330-----11	16834	4838,09
E17594010000000000000055473200001	Herrenberg	71083	SgK33410----11	1266	363,85
E17594010000000000000055473200001	Herrenberg	71083	SgK33420----11	-1266	-207,37
E17594010000000000000055541800001	Herrenberg	71083	SgK330-----11	9696	2786,63
E17594010000000000000055629000001	Herrenberg	71083	SgK330-----11	15082	4334,57
E17594010000000000000055652400001	Herrenberg	71083	SgK330-----11	24088,6	6923,06
E17594010000000000000055652400001	Herrenberg	71083	SgK331-----11	49863,4	13627,67
E17594010000000000000055652400001	Herrenberg	71083	SgK33410----11	7987,9	2295,72
E17594010000000000000055652400001	Herrenberg	71083	SgK33411----11	16535,1	4519,04
E17594010000000000000055652400001	Herrenberg	71083	SgK33420----11	-7987,9	-1308,42
E17594010000000000000055652400001	Herrenberg	71083	SgK33421----11	-16535,1	-2708,45
E17594010000000000000055676200001	Herrenberg	71083	SgK330-----11	14123	4058,95
E17594010000000000000055676200001	Herrenberg	71083	SgK331-----11	21467	5866,93
E17594010000000000000055676200001	Herrenberg	71083	SgK33410----11	21065,4	6054,2
E17594010000000000000055676200001	Herrenberg	71083	SgK33411----11	32019,6	8750,95
E17594010000000000000055676200001	Herrenberg	71083	SgK33420----11	-10556,7	-1729,19
E17594010000000000000055676200001	Herrenberg	71083	SgK33421----11	-16046,3	-2628,38
E17594010000000000000055676200001	Herrenberg	71083	SgK33430----11	-10508,7	-1261,04
E17594010000000000000055676200001	Herrenberg	71083	SgK33431----11	-15973,3	-1916,8
E17594010000000000000055706900001	Herrenberg	71083	SgK330-----11	2795	803,28
E17594010000000000000055706900001	Herrenberg	71083	SgK33410----11	1028	295,45
E17594010000000000000055706900001	Herrenberg	71083	SgK33420----11	-1028	-168,39
E17594010000000000000055724500001	Herrenberg	71083	SgK330-----11	4755	1366,59
E17594010000000000000055724500001	Herrenberg	71083	SgK33410----11	603	173,3
E17594010000000000000055724500001	Herrenberg	71083	SgK33420----11	-603	-98,77
E17594010000000000000055739100001	Herrenberg	71083	SgK330-----11	12911	3710,62

E17594010000000000000055739100001	Herrenberg	71083	SgK33410----11	1839	528,53
E17594010000000000000055739100001	Herrenberg	71083	SgK33420----11	-1839	-301,23
E17594010000000000000055798300001	Herrenberg	71083	SgK330-----11	11152	3205,08
E17594010000000000000055823100001	Herrenberg	71083	SgK330-----11	3913	1124,6
E17594010000000000000055823100001	Herrenberg	71083	SgK33410----11	1326	381,09
E17594010000000000000055823100001	Herrenberg	71083	SgK33420----11	-1326	-217,2
E17594010000000000000055904100001	Herrenberg	71083	SgK330-----11	10186	2927,46
E17594010000000000000056032800001	Herrenberg	71083	SgK330-----11	10536	3028,05
E17594010000000000000056032800001	Herrenberg	71083	SgK33410----11	2272	652,97
E17594010000000000000056032800001	Herrenberg	71083	SgK33420----11	-2272	-372,15
E17594010000000000000056288300001	Herrenberg	71083	SgK330-----11	11148	3203,94
E17594010000000000000056288300001	Herrenberg	71083	SgK33410----11	3249	933,76
E17594010000000000000056288300001	Herrenberg	71083	SgK33420----11	-3249	-532,19
E17594010000000000000056310200001	Herrenberg	71083	SgK330-----11	7665	2202,92
E17594010000000000000056310200001	Herrenberg	71083	SgK33410----11	1706	490,3
E17594010000000000000056310200001	Herrenberg	71083	SgK33420----11	-1706	-279,44
E17594010000000000000056362700001	Herrenberg	71083	SgK330-----11	4957	1424,64
E17594010000000000000056362700001	Herrenberg	71083	SgK33410----11	1188	341,43
E17594010000000000000056362700001	Herrenberg	71083	SgK33420----11	-1188	-194,59
E17594010000000000000056494400001	Herrenberg	71083	SgK330-----11	33618,4	9661,93
E17594010000000000000056494400001	Herrenberg	71083	SgK331-----11	21179,59	5788,38
E17594010000000000000056560300001	Herrenberg	71083	SgK330-----11	7141	2052,32
E17594010000000000000056586500001	Herrenberg	71083	SgK330-----11	10380	2983,21
E17594010000000000000056586500001	Herrenberg	71083	SgK33410----11	1756	504,67
E17594010000000000000056586500001	Herrenberg	71083	SgK33420----11	-1756	-287,63
E17594010000000000000056586900001	Herrenberg	71083	SgK330-----11	5871	1687,33
E17594010000000000000056586900001	Herrenberg	71083	SgK33410----11	2649	761,32
E17594010000000000000056586900001	Herrenberg	71083	SgK33420----11	-2556	-418,67
E17594010000000000000056586900001	Herrenberg	71083	SgK33430---11	-93	-11,16
E17594010000000000000056784300001	Herrenberg	71083	SgK330-----11	2712	779,43
E17594010000000000000056784300001	Herrenberg	71083	SgK33410----11	1522	437,42
E17594010000000000000056784300001	Herrenberg	71083	SgK33420----11	-1270	-208,03
E17594010000000000000056784300001	Herrenberg	71083	SgK33430---11	-252	-30,24
E17594010000000000000056847300001	Herrenberg	71083	SgK330-----11	5132	1474,94
E17594010000000000000056999700001	Herrenberg	71083	SgK330-----11	5149	1479,82
E17594010000000000000056999700001	Herrenberg	71083	SgK33410----11	1132	325,34
E17594010000000000000056999700001	Herrenberg	71083	SgK33420----11	-1132	-185,42
E17594010000000000000057071400001	Herrenberg	71083	SgK330-----11	4701	1351,07
E17594010000000000000057071400001	Herrenberg	71083	SgK33410----11	1623	466,45
E17594010000000000000057071400001	Herrenberg	71083	SgK33420----11	-1623	-265,85
E17594010000000000000057104600001	Herrenberg	71083	SgK330-----11	8015	2303,51
E17594010000000000000057104600001	Herrenberg	71083	SgK33410----11	976	280,5
E17594010000000000000057104600001	Herrenberg	71083	SgK33420----11	-976	-159,87
E17594010000000000000057126300001	Herrenberg	71083	SgK331-----11	12145	3319,23
E17594010000000000000057126300001	Herrenberg	71083	SgK33411----11	6178	1688,45
E17594010000000000000057126300001	Herrenberg	71083	SgK33421----11	-5497	-900,41
E17594010000000000000057126300001	Herrenberg	71083	SgK33431---11	-681	-81,72
E17594010000000000000057131700001	Herrenberg	71083	SgK330-----11	32348,68	9297,01
E17594010000000000000057131700001	Herrenberg	71083	SgK331-----11	2070,31	565,82
E17594010000000000000057183300001	Herrenberg	71083	SgK330-----11	10609	3049,03
E17594010000000000000057183300001	Herrenberg	71083	SgK33410----11	246	70,7

E17594010000000000000057183300001	Herrenberg	71083	SgK33420----11	-246	-40,29
E17594010000000000000057288500001	Herrenberg	71083	SgK330-----11	5915	1699,97
E17594010000000000000057288700001	Herrenberg	71083	SgK330-----11	12822	3685,04
E17594010000000000000057397600001	Herrenberg	71083	SgK330-----11	12275	3527,84
E17594010000000000000057484600001	Herrenberg	71083	SgK330-----11	2611	750,4
E17594010000000000000057484600001	Herrenberg	71083	SgK33410----11	2483	713,62
E17594010000000000000057484600001	Herrenberg	71083	SgK33420----11	-1528	-250,29
E17594010000000000000057484600001	Herrenberg	71083	SgK33430----11	-955	-114,6
E17594010000000000000057583500001	Herrenberg	71083	SgK330-----11	7522	2161,82
E17594010000000000000057583500001	Herrenberg	71083	SgK33410----11	860	247,16
E17594010000000000000057583500001	Herrenberg	71083	SgK33420----11	-860	-140,87
E17594010000000000000057611600001	Herrenberg	71083	SgK330-----11	32009	9199,39
E17594010000000000000057611600001	Herrenberg	71083	SgK33410----11	4961	1425,79
E17594010000000000000057611600001	Herrenberg	71083	SgK33420----11	-4961	-812,61
E17594010000000000000057613300001	Herrenberg	71083	SgK330-----11	2576	740,34
E17594010000000000000057613300001	Herrenberg	71083	SgK33410----11	1292	371,32
E17594010000000000000057613300001	Herrenberg	71083	SgK33420----11	-1160	-190,01
E17594010000000000000057613300001	Herrenberg	71083	SgK33430----11	-132	-15,84
E17594010000000000000057649700001	Herrenberg	71083	SgK330-----11	6790	1951,45
E17594010000000000000057649700001	Herrenberg	71083	SgK33410----11	864	248,31
E17594010000000000000057649700001	Herrenberg	71083	SgK33420----11	-864	-141,52
E17594010000000000000057695900001	Herrenberg	71083	SgK330-----11	8129	2336,27
E17594010000000000000057724900001	Herrenberg	71083	SgK330-----11	2600	747,24
E17594010000000000000057724900001	Herrenberg	71083	SgK33410----11	1521	437,14
E17594010000000000000057724900001	Herrenberg	71083	SgK33420----11	-1236	-202,46
E17594010000000000000057724900001	Herrenberg	71083	SgK33430----11	-285	-34,2
E17594010000000000000057729000001	Herrenberg	71083	SgK330-----11	3586	1030,62
E17594010000000000000057774900001	Herrenberg	71083	SgK330-----11	3539	1017,11
E17594010000000000000057774900001	Herrenberg	71083	SgK33410----11	998	286,83
E17594010000000000000057774900001	Herrenberg	71083	SgK33420----11	-998	-163,47
E17594010000000000000057806700001	Herrenberg	71083	SgK330-----11	5410	1554,83
E17594010000000000000057806700001	Herrenberg	71083	SgK33410----11	2308	663,32
E17594010000000000000057806700001	Herrenberg	71083	SgK33420----11	-2308	-378,05
E17594010000000000000057933500001	Herrenberg	71083	SgK330-----11	26535,8	7626,39
E17594010000000000000057933500001	Herrenberg	71083	SgK331-----11	20229,2	5528,64
E17594010000000000000057933500001	Herrenberg	71083	SgK33410----11	3617,4	1039,64
E17594010000000000000057933500001	Herrenberg	71083	SgK33411----11	2757,6	753,65
E17594010000000000000057933500001	Herrenberg	71083	SgK33420----11	-3617,4	-592,53
E17594010000000000000057933500001	Herrenberg	71083	SgK33421----11	-2757,6	-451,69
E17594010000000000000058137300001	Herrenberg	71083	SgK330-----11	3685	1059,07
E17594010000000000000058137300001	Herrenberg	71083	SgK33410----11	8199	2356,39
E17594010000000000000058137300001	Herrenberg	71083	SgK33420----11	-3565	-583,95
E17594010000000000000058137300001	Herrenberg	71083	SgK33430----11	-4634	-556,08
E17594010000000000000058141700001	Herrenberg	71083	SgK330-----11	1253	360,11
E17594010000000000000058141700001	Herrenberg	71083	SgK33410----11	3435	987,21
E17594010000000000000058141700001	Herrenberg	71083	SgK33420----11	-1406	-230,3
E17594010000000000000058141700001	Herrenberg	71083	SgK33430----11	-2029	-243,48
E17594010000000000000058305100001	Herrenberg	71083	SgK330-----11	27944,99	8031,39
E17594010000000000000058305100001	Herrenberg	71083	SgK331-----11	7955	2174,1
E17594010000000000000058340500001	Herrenberg	71083	SgK330-----11	7161	2058,07
E17594010000000000000058340500001	Herrenberg	71083	SgK33410----11	2038	585,72

E17594010000000000000058340500001	Herrenberg	71083	SgK33420----11	-2038	-333,82
E17594010000000000000058370700001	Herrenberg	71083	SgK330-----11	18218	5235,85
E17594010000000000000058500500001	Herrenberg	71083	SgK330-----11	9886	2841,24
E17594010000000000000058522800001	Herrenberg	71083	SgK330-----11	3833	1101,6
E17594010000000000000058522800001	Herrenberg	71083	SgK33410----11	675	194
E17594010000000000000058522800001	Herrenberg	71083	SgK33420----11	-675	-110,57
E17594010000000000000058840900001	Herrenberg	71083	SgK330-----11	7618	2189,41
E17594010000000000000058840900001	Herrenberg	71083	SgK33410----11	1196	343,73
E17594010000000000000058840900001	Herrenberg	71083	SgK33420----11	-1196	-195,9
E17594010000000000000058957400001	Herrenberg	71083	SgK330-----12	9496	2319,87
E17594010000000000000059039400001	Herrenberg	71083	SgK330-----12	2115	516,69
E17594010000000000000059039400001	Herrenberg	71083	SgK33410----12	848	207,17
E17594010000000000000059039400001	Herrenberg	71083	SgK33420----12	-848	-138,9
E17594010000000000000059092000001	Herrenberg	71083	SgK330-----12	6180	1509,77
E17594010000000000000059092000001	Herrenberg	71083	SgK33410----12	885	216,21
E17594010000000000000059092000001	Herrenberg	71083	SgK33420----12	-885	-144,96
E17594010000000000000059092400001	Herrenberg	71083	SgK330-----12	4039	986,73
E17594010000000000000059092400001	Herrenberg	71083	SgK33410----12	1245	304,15
E17594010000000000000059092400001	Herrenberg	71083	SgK33420----12	-1245	-203,93
E17594010000000000000059102100001	Herrenberg	71083	SgK330-----12	4239	1035,59
E17594010000000000000059102100001	Herrenberg	71083	SgK33410----12	1938	473,46
E17594010000000000000059102100001	Herrenberg	71083	SgK33420----12	-1853	-303,52
E17594010000000000000059102100001	Herrenberg	71083	SgK33430----12	-85	-10,2
E17594010000000000000059241000001	Herrenberg	71083	SgK330-----12	3170	774,43
E17594010000000000000059241000001	Herrenberg	71083	SgK33410----12	900	219,87
E17594010000000000000059241000001	Herrenberg	71083	SgK33420----12	-900	-147,42
E17594010000000000000059356100001	Herrenberg	71083	SgK330-----12	4060	991,86
E17594010000000000000059356100001	Herrenberg	71083	SgK33410----12	941	229,89
E17594010000000000000059356100001	Herrenberg	71083	SgK33420----12	-941	-154,14
E17594010000000000000059469700001	Herrenberg	71083	SgK330-----12	7718	1885,51
E17594010000000000000059469700001	Herrenberg	71083	SgK33410----12	1204	294,14
E17594010000000000000059469700001	Herrenberg	71083	SgK33420----12	-1204	-197,22
E17594010000000000000059609800001	Herrenberg	71083	SgK330-----12	2644	645,93
E17594010000000000000059609800001	Herrenberg	71083	SgK33410----12	1144	279,47
E17594010000000000000059609800001	Herrenberg	71083	SgK33420----12	-1136	-186,08
E17594010000000000000059609800001	Herrenberg	71083	SgK33430----12	-8	-0,96
E17594010000000000000059947200001	Herrenberg	71083	SgK330-----12	5886	1437,95
E17594010000000000000059947200001	Herrenberg	71083	SgK33410----12	1454	355,21
E17594010000000000000059947200001	Herrenberg	71083	SgK33420----12	-1454	-238,17
E17594010000000000000059965900001	Herrenberg	71083	SgK330-----12	2395	585,1
E17594010000000000000059965900001	Herrenberg	71083	SgK33410----12	1409	344,22
E17594010000000000000059965900001	Herrenberg	71083	SgK33420----12	-1141	-186,9
E17594010000000000000059965900001	Herrenberg	71083	SgK33430----12	-268	-32,16
E17594010000000000000060353700001	Herrenberg	71083	SgK330-----12	6621	1617,51
E17594010000000000000060550800001	Herrenberg	71083	SgK330-----12	2895	707,25
E17594010000000000000060550800001	Herrenberg	71083	SgK33410----12	1342	327,86
E17594010000000000000060550800001	Herrenberg	71083	SgK33420----12	-1271	-208,19
E17594010000000000000060550800001	Herrenberg	71083	SgK33430----12	-71	-8,52
E17594010000000000000060580400001	Herrenberg	71083	SgK330-----12	6907	1687,38
E17594010000000000000060580400001	Herrenberg	71083	SgK33410----12	330	80,62
E17594010000000000000060580400001	Herrenberg	71083	SgK33420----12	-330	-54,05

E175940100000000000000060933300001	Herrenberg	71083	SgK330-----12	4588	1120,85
E175940100000000000000060933300001	Herrenberg	71083	SgK33410----12	785	191,78
E175940100000000000000060933300001	Herrenberg	71083	SgK33420----12	-785	-128,58
E175940100000000000000061075500001	Herrenberg	71083	SgK3220--Apr12	2904	566,28
E175940100000000000000061185300001	Herrenberg	71083	SgK3220--Apr12	3325	648,38
E175940100000000000000061320500001	Herrenberg	71083	SgK330-----12	3803	929,07
E175940100000000000000061501800001	Herrenberg	71083	SgK3220--Mai12	6484	1252,06
E175940100000000000000061545200001	Herrenberg	71083	SgK330-----12	508	124,1
E175940100000000000000061545200001	Herrenberg	71083	SgK33410----12	3197	781,03
E175940100000000000000061545200001	Herrenberg	71083	SgK33420----12	-1112	-182,15
E175940100000000000000061545200001	Herrenberg	71083	SgK33430----12	-2085	-250,2
E175940100000000000000061603200001	Herrenberg	71083	SgK3220--Mai12	4759	918,96
E175940100000000000000061988700001	Herrenberg	71083	SgK3220--Jun12	3526	673,82
E175940100000000000000062345900001	Herrenberg	71083	SgK3220--Jun12	1851	353,73
E175940100000000000000062596200001	Herrenberg	71083	SgK3220--Jun12	1350	257,99
E175940100000000000000062743200001	Herrenberg	71083	SgK3220--Jul12	1089	206,04
E175940100000000000000062930900001	Herrenberg	71083	SgK3220--Jul12	2862	541,49
E175940100000000000000063045400001	Herrenberg	71083	SgK3220--Jul12	834	157,79
E175940100000000000000063190300001	Herrenberg	71083	SgK3220--Jul12	2857,23	540,59
E175940100000000000000063190300001	Herrenberg	71083	SgK3221--Jul12	1785,76	320,55
E175940100000000000000063813400001	Herrenberg	71083	SgK3220--Aug12	1930,21	361,53
E175940100000000000000063813400001	Herrenberg	71083	SgK3221--Aug12	337,78	60,02
E175940100000000000000064178600001	Herrenberg	71083	SgK3220--Sep12	646	119,77
E175940100000000000000064180600001	Herrenberg	71083	SgK3220--Sep12	881,95	163,51
E175940100000000000000064180600001	Herrenberg	71083	SgK3221--Sep12	291,04	51,19
E175940100000000000000064190700001	Herrenberg	71083	SgK3220--Sep12	907,16	168,19
E175940100000000000000064190700001	Herrenberg	71083	SgK3221--Sep12	118,83	20,9
E175940100000000000000064263000001	Herrenberg	71083	SgK3220--Okt12	325	59,67
E175940100000000000000064283200001	Herrenberg	71083	SgK3220--Sep12	463	85,84
E175940100000000000000064358400001	Herrenberg	71083	SgK3220--Sep12	709	131,45
E175940100000000000000064397000001	Herrenberg	71083	SgK3220--Sep12	896,32	166,18
E175940100000000000000064397000001	Herrenberg	71083	SgK3221--Sep12	201,67	35,47
E175940100000000000000064859600001	Herrenberg	71083	SgK3220--Sep12	718	133,12
E175940100000000000000065003600001	Herrenberg	71083	SgK3220--Okt12	178	32,68
E175940100000000000000065004100001	Herrenberg	71083	SgK3220--Okt12	647	118,79
E175940100000000000000065085900001	Herrenberg	71083	SgK3220--Okt12	173	31,76
E175940100000000000000065365400001	Herrenberg	71083	SgK3220--Okt12	259	47,55
E175940100000000000000065530900001	Herrenberg	71083	SgK3220--Nov12	13	2,33
E175940100000000000000065558600001	Herrenberg	71083	SgK3220--Nov12	109	19,51
E1084301000ZE000000271890RA000001	Herrenberg	71083	SoK81a-----01	2600	1316,12
E1084301000ZE000000271893RA000001	Herrenberg	71083	SoK81a-----01	1292	654,01
E1084301000ZE000000272699RA000001	Herrenberg	71083	SoK81a-----01	1068	540,62
E1084301000ZE000000133178RA000001	Herrenberg	71083	SoK81a-----01	1850	936,47
E1084301000ZE000000124653RA000001	Herrenberg	71083	SoK81a-----01	8733	4420,64
E1084301000ZE000000272784RA000001	Herrenberg	71083	SoK81a-----01	1169	591,75
E1084301000ZE000000272820RA000001	Herrenberg	71083	SoK81a-----01	2850	1442,67
E1084301000ZE000000273377RA000001	Herrenberg	71083	SoK81a-----01	2720	1376,86
E1084301000ZE000000273417RA000001	Herrenberg	71083	SoK81a-----01	1612	815,99
E1084301000ZE000000273420RA000001	Herrenberg	71083	SoK81a-----01	2450	1240,19
E1084301000ZE000000264189RA000001	Herrenberg	71083	SoK81a-----01	1143	578,59
E1084301000ZE000000273479RA000001	Herrenberg	71083	SoK81a-----01	1890	956,72

E1084301000ZE000000273505RA000001	Herrenberg	71083	SoK81a-----01	2346	1187,55
E1084301000ZE000000412603RA000001	Herrenberg	71083	SoK81a-----01	1041	526,95
E1084301000ZE000000123896RA000001	Herrenberg	71083	SoK81a-----01	1745	883,32
E1084301000ZE000000121894RA000001	Herrenberg	71083	SoK81a-----01	2052	1038,72
E1084301000ZE000000124631RA000001	Herrenberg	71083	SoK81a-----01	1069	541,13
E1084301000ZE000000125415RA000001	Herrenberg	71083	SoK81a-----01	1231	623,13
E1084301000ZE000000125758RA000001	Herrenberg	71083	SoK81a-----01	2791	1412,8
E1084301000ZE000000126361RA000001	Herrenberg	71083	SoK81a-----01	6312	3195,13
E1084301000ZE000000273598RA000001	Herrenberg	71083	SoK81a-----01	128	64,79
E1084301000ZE000000125143RA000001	Herrenberg	71083	SoK81a-----01	2315	1171,85
E1084301000ZE000000183581RA000001	Herrenberg	71083	SoK81a-----02	1965	945,17
E1084301000ZE000000184422RA000001	Herrenberg	71083	SoK81a-----02	12294	5913,41
E1084301000ZE000000184421RA000001	Herrenberg	71083	SoK81a-----02	13589	6536,33
E1084301000ZE000000200801RA000001	Herrenberg	71083	SoK81a-----02	1848	888,89
E1084301000ZE000000208487RA000001	Herrenberg	71083	SoK81a-----02	2116	1017,8
E1084301000ZE000000279810RA000001	Herrenberg	71083	SoK81a-----02	2546	1224,63
E1084301000ZE000000279877RA000001	Herrenberg	71083	SoK81a-----02	4660	2241,46
E1084301000ZE000000273901RA000001	Herrenberg	71083	SoK81a-----02	5805	2792,2
E1084301000ZE000000273902RA000001	Herrenberg	71083	SoK81a-----02	5720	2751,33
E1084301000ZE000000273903RA000001	Herrenberg	71083	SoK81a-----02	3874	1863,4
E1084301000ZE000000273904RA000001	Herrenberg	71083	SoK81a-----02	5876	2826,35
E1084301000ZE000000273905RA000001	Herrenberg	71083	SoK81a-----02	3803	1829,28
E1084301000ZE000000273906RA000001	Herrenberg	71083	SoK81a-----02	5793	2786,43
E1084301000ZE000000289739RA000001	Herrenberg	71083	SoK81a-----02	3679	1769,6
E1084301000ZE000000337225RA000001	Herrenberg	71083	SoK81a-----03	4156	1899,29
E1084301000ZE000000343625RA000001	Herrenberg	71083	SoK81a-----03	2384	1089,49
E1084301000ZE000000345459RA000001	Herrenberg	71083	SoK81a-----03	8671	3962,65
E1084301000ZE000000343225RA000001	Herrenberg	71083	SoK81a-----03	1888	862,82
E1084301000ZE000000381941RA000001	Herrenberg	71083	SoK111-----04	2773	1591,7
E1084301000ZE000000383021RA000001	Herrenberg	71083	SoK111-----04	6822	3915,83
E1084301000ZE000000383549RA000001	Herrenberg	71083	SoK111-----04	21108	12115,99
E1084301000ZE000000408145RA000001	Herrenberg	71083	SoK111-----04	5434	3119,12
E1084301000ZE000000398628RA000001	Herrenberg	71083	SoK111-----04	3526	2023,92
E1084301000ZE000000401449RA000001	Herrenberg	71083	SoK111-----04	2453	1408,02
E1084301000ZE000000409782RA000001	Herrenberg	71083	SoK111-----04	30547	17533,98
E1084301000ZE000000409782RA000001	Herrenberg	71083	SoK112-----04	672	366,91
E1084301000ZE000000412707RA000001	Herrenberg	71083	SoK111-----04	25718	14762,13
E1084301000000000000000003873900001	Herrenberg	71083	SoK111-----04	3980	2284,52
E1084301000ZE000000420046RA000001	Herrenberg	71083	SoK111-----04	29242,2	16785,02
E1084301000ZE000000420046RA000001	Herrenberg	71083	SoK112-----04	4561,8	2490,74
E1084301000ZE000000427943RA000001	Herrenberg	71083	SoK111-----04	17999	10331,42
E1084301000ZE000000427945RA000001	Herrenberg	71083	SoK111-----04	7242	4156,91
E1084301000ZE000000431646RA000001	Herrenberg	71083	SoK111-----04	7939	4556,99
E1084301000ZE000000441509RA000001	Herrenberg	71083	SoK111-----04	7883	4524,84
E108430100000000000000006189100001	Herrenberg	71083	SoK111-----05	1450	790,69
E1084301000ZE000000441674RA000001	Herrenberg	71083	SoK111-----04	4507	2587,02
E1084301000ZE000000441675RA000001	Herrenberg	71083	SoK111-----04	3932	2256,97
E1084301000ZE000000441936RA000001	Herrenberg	71083	SoK111-----04	20001	11480,57
E1084301000ZE000000442037RA000001	Herrenberg	71083	SoK111-----05	9616	5243,6
E1084301000ZE000000442199RA000001	Herrenberg	71083	SoK111-----04	5451	3128,87
E1084301000ZE000000442560RA000001	Herrenberg	71083	SoK111-----04	5378	3086,97

E1084301000ZE000000442540RA000001	Herrenberg	71083	SoK111-----04	6427	3689,1
E1084301000ZE000000442600RA000001	Herrenberg	71083	SoK111-----04	11134	6390,92
E1084301000ZE000000442922RA000001	Herrenberg	71083	SoK111-----04	1153	661,82
E1084301000ZE000000442962RA000001	Herrenberg	71083	SoK111-----04	5341	3065,73
E1084301000ZE000000443184RA000001	Herrenberg	71083	SoK111-----04	11037	6335,24
E1084301000ZE000000443225RA000001	Herrenberg	71083	SoK111-----04	3025	1736,35
E1084301000ZE000000443226RA000001	Herrenberg	71083	SoK111-----04	2330	1337,42
E1084301000ZE000000443364RA000001	Herrenberg	71083	SoK111-----04	2603	1494,12
E10843010000000000000008543300001	Herrenberg	71083	SoK111-----05	4265	2325,7
E10843010000000000000008714800001	Herrenberg	71083	SoK111-----05	26202	14287,95
E10843010000000000000009215400001	Herrenberg	71083	SoK111-----05	2652	1446,14
E10843010000000000000009218200001	Herrenberg	71083	SoK111-----05	2487	1356,16
E10843010000000000000009220800001	Herrenberg	71083	SoK111-----05	2850	1554,11
E10843010000000000000009830300001	Herrenberg	71083	SoK111-----05	2101	1145,68
E10843010000000000000009929400001	Herrenberg	71083	SoK111-----05	3960	2159,39
E10843010000000000000010192600001	Herrenberg	71083	SoK111-----05	9580	5223,97
E10843010000000000000010505300001	Herrenberg	71083	SoK111-----05	5358	2921,72
E10843010000000000000010546300001	Herrenberg	71083	SoK111-----05	19748	10768,58
E10843010000000000000010546400001	Herrenberg	71083	SoK111-----05	4409	2404,23
E10843010000000000000010706300001	Herrenberg	71083	SoK111-----05	7892	4303,51
E10843010000000000000010774200001	Herrenberg	71083	SoK111-----05	2444	1332,71
E10843010000000000000010853100001	Herrenberg	71083	SoK111-----05	4617	2517,65
E10843010000000000000010932900001	Herrenberg	71083	SoK111-----05	4065	2216,64
E10843010000000000000011225900001	Herrenberg	71083	SoK111-----05	4448	2425,49
E10843010000000000000011556700001	Herrenberg	71083	SoK111-----05	8879	4841,72
E10843010000000000000011577500001	Herrenberg	71083	SoK111-----05	5180	2824,65
E10843010000000000000011746000001	Herrenberg	71083	SoK111-----05	3365	1834,93
E10843010000000000000011734500001	Herrenberg	71083	SoK111-----05	1993	1086,78
E10843010000000000000012126600001	Herrenberg	71083	SoK111-----05	4058	2212,83
E10843010000000000000012342400001	Herrenberg	71083	SoK111-----05	8831	4815,54
E10843010000000000000012546800001	Herrenberg	71083	SoK111-----05	17620	9608,19
E10843010000000000000012744100001	Herrenberg	71083	SoK111-----05	3165	1725,87
E10843010000000000000012873700001	Herrenberg	71083	SoK111-----05	3898	2125,58
E10843010000000000000013125000001	Herrenberg	71083	SoK111-----05	4879	2660,52
E10843010000000000000013181600001	Herrenberg	71083	SoK111-----05	3924	2139,76
E10843010000000000000013411200001	Herrenberg	71083	SoK111-----05	3782	2062,32
E10843010000000000000013681600001	Herrenberg	71083	SoK111-----05	9614	5242,51
E10843010000000000000013736700001	Herrenberg	71083	SoK111-----05	11362	6195,7
E10843010000000000000013864300001	Herrenberg	71083	SoK111-----05	9375	5112,19
E10843010000000000000014157300001	Herrenberg	71083	SoK111-----05	4183	2280,99
E10843010000000000000014183200001	Herrenberg	71083	SoK111-----05	5743	3131,66
E10843010000000000000014234900001	Herrenberg	71083	SoK111-----05	7155	3901,62
E10843010000000000000014614100001	Herrenberg	71083	SoK111-----05	8831	4815,54
E10843010000000000000014620000001	Herrenberg	71083	SoK111-----05	5425	2958,25
E10843010000000000000014696200001	Herrenberg	71083	SoK111-----05	2712	1478,85
E10843010000000000000014997100001	Herrenberg	71083	SoK111-----05	10713	5841,8
E10843010000000000000014997300001	Herrenberg	71083	SoK111-----05	4470	2437,49
E10843010000000000000015700500001	Herrenberg	71083	SoK111-----05	6735	3672,6
E10843010000000000000015912900001	Herrenberg	71083	SoK111-----06	8641	4476,04
E10843010000000000000015929000001	Herrenberg	71083	SoK111-----06	14154	7331,77
E10843010000000000000016319200001	Herrenberg	71083	SoK111-----06	10508	5443,14

E10843010000000000000000016319300001	Herrenberg	71083	SoK111-----06	6320	3273,76
E10843010000000000000000016475200001	Herrenberg	71083	SoK111-----06	8272	4284,9
E10843010000000000000000016651400001	Herrenberg	71083	SoK111-----06	8242	4269,36
E10843010000000000000000016815200001	Herrenberg	71083	SoK111-----06	8094	4192,69
E10843010000000000000000017048500001	Herrenberg	71083	SoK111-----06	4490	2325,82
E10843010000000000000000017089200001	Herrenberg	71083	SoK111-----06	13016	6742,29
E10843010000000000000000017183600001	Herrenberg	71083	SoK111-----06	5663	2933,43
E10843010000000000000000017257900001	Herrenberg	71083	SoK111-----06	3244	1680,39
E10843010000000000000000017408100001	Herrenberg	71083	SoK111-----06	7108	3681,94
E10843010000000000000000017559300001	Herrenberg	71083	SoK111-----06	8447	4375,55
E10843010000000000000000017598400001	Herrenberg	71083	SoK111-----06	1986	1028,75
E10843010000000000000000017606200001	Herrenberg	71083	SoK111-----06	8864	4591,55
E10843010000000000000000017639700001	Herrenberg	71083	SoK111-----06	7965	4125,87
E10843010000000000000000017639800001	Herrenberg	71083	SoK111-----06	3669	1900,54
E10843010000000000000000018015800001	Herrenberg	71083	SoK111-----06	11708	6064,74
E10843010000000000000000018057500001	Herrenberg	71083	SoK111-----06	12683	6569,79
E10843010000000000000000018075900001	Herrenberg	71083	SoK111-----06	5296	2743,33
E10843010000000000000000018091600001	Herrenberg	71083	SoK111-----06	5568	2884,22
E10843010000000000000000018479000001	Herrenberg	71083	SoK111-----06	9257	4795,13
E10843010000000000000000018506900001	Herrenberg	71083	SoK111-----06	11294	5850,29
E10843010000000000000000018591000001	Herrenberg	71083	SoK111-----06	3448	1786,06
E10843010000000000000000018594400001	Herrenberg	71083	SoK111-----06	16135	8357,93
E10843010000000000000000018713700001	Herrenberg	71083	SoK111-----06	4565	2364,67
E10843010000000000000000018720400001	Herrenberg	71083	SoK111-----06	4543	2353,27
E10843010000000000000000018725000001	Herrenberg	71083	SoK111-----06	5678	2941,2
E10843010000000000000000018865200001	Herrenberg	71083	SoK111-----06	2649	1372,18
E10843010000000000000000018942900001	Herrenberg	71083	SoK111-----06	14953	7745,65
E10843010000000000000000019236300001	Herrenberg	71083	SoK111-----06	2706	1401,71
E10843010000000000000000019657200001	Herrenberg	71083	SoK111-----06	10854	5622,37
E10843010000000000000000019961900001	Herrenberg	71083	SoK111-----06	13349	6914,78
E10843010000000000000000019962000001	Herrenberg	71083	SoK111-----06	3650	1890,7
E10843010000000000000000020006400001	Herrenberg	71083	SoK111-----06	27749	14373,98
E10843010000000000000000020021000001	Herrenberg	71083	SoK111-----06	10942	5667,96
E10843010000000000000000020158800001	Herrenberg	71083	SoK111-----06	6861	3554
E10843010000000000000000020317600001	Herrenberg	71083	SoK111-----06	9781	5066,56
E10843010000000000000000020318100001	Herrenberg	71083	SoK111-----06	24065	12465,67
E10843010000000000000000020408500001	Herrenberg	71083	SoK111-----06	3401	1761,72
E10843010000000000000000020494500001	Herrenberg	71083	SoK111-----06	8668	4490,02
E10843010000000000000000020659800001	Herrenberg	71083	SoK111-----06	7243	3751,87
E10843010000000000000000020716300001	Herrenberg	71083	SoK111-----06	4487	2324,27
E10843010000000000000000020847500001	Herrenberg	71083	SoK111-----06	8332	4315,98
E10843010000000000000000020865200001	Herrenberg	71083	SoK111-----06	10206	5286,71
E10843010000000000000000020870100001	Herrenberg	71083	SoK111-----06	7407	3836,83
E10843010000000000000000021127000001	Herrenberg	71083	SoK111-----06	4917	2547,01
E10843010000000000000000021494900001	Herrenberg	71083	SoK111-----06	6943	3596,47
E10843010000000000000000021624300001	Herrenberg	71083	SoK111-----06	4933	2555,29
E10843010000000000000000021624400001	Herrenberg	71083	SoK111-----06	9156	4742,81
E10843010000000000000000021720900001	Herrenberg	71083	SoK111-----06	4345	2250,71
E10843010000000000000000022218800001	Herrenberg	71083	SoK111-----06	3444	1783,99
E10843010000000000000000022523600001	Herrenberg	71083	SoK111-----06	26947	13958,55
E10843010000000000000000022559000001	Herrenberg	71083	SoK111-----06	9253	4793,05

E108430100000000000000022553800001	Herrenberg	71083	SoK111-----06	7221	3740,48
E108430100000000000000022553900001	Herrenberg	71083	SoK114-----06	941	534,49
E108430100000000000000022701000001	Herrenberg	71083	SoK111-----06	6646	3442,63
E108430100000000000000022748300001	Herrenberg	71083	SoK111-----07	8316	4092,3
E108430100000000000000022980100001	Herrenberg	71083	SoK111-----07	31343	15423,9
E108430100000000000000023511600001	Herrenberg	71083	SoK111-----07	8464	4165,13
E108430100000000000000023766100001	Herrenberg	71083	SoK111-----07	22657	11149,51
E108430100000000000000023766300001	Herrenberg	71083	SoK111-----07	24085	11852,23
E108430100000000000000023865900001	Herrenberg	71083	SoK111-----07	12654	6227,03
E108430100000000000000024181000001	Herrenberg	71083	SoK111-----07	3847	1893,11
E108430100000000000000024259100001	Herrenberg	71083	SoK111-----07	1892	931,05
E108430100000000000000024472500001	Herrenberg	71083	SoK111-----07	15465	7610,33
E108430100000000000000024479400001	Herrenberg	71083	SoK111-----07	4142	2038,28
E108430100000000000000024571300001	Herrenberg	71083	SoK111-----07	13776	6779,17
E108430100000000000000024822200001	Herrenberg	71083	SoK111-----07	25491	12544,12
E108430100000000000000024896600001	Herrenberg	71083	SoK111-----07	23429	11529,41
E108430100000000000000024917900001	Herrenberg	71083	SoK111-----07	9840	4842,26
E108430100000000000000025235500001	Herrenberg	71083	SoK111-----07	20564	10119,54
E108430100000000000000025294700001	Herrenberg	71083	SoK111-----07	16992	8361,76
E108430100000000000000025472100001	Herrenberg	71083	SoK111-----07	7142	3514,58
E108430100000000000000025605500001	Herrenberg	71083	SoK111-----07	3816	1877,85
E108430100000000000000025822800001	Herrenberg	71083	SoK111-----07	6042	2973,27
E108430100000000000000025829900001	Herrenberg	71083	SoK111-----07	5660	2785,29
E1084301E10ZE000000124653RA000001	Herrenberg	71083	SoK111-----07	14805	7285,54
E108430100000000000000026109200001	Herrenberg	71083	SoK111-----07	8530	4197,61
E108430100000000000000026155800001	Herrenberg	71083	SoK111-----07	3432	1688,89
E108430100000000000000026307300001	Herrenberg	71083	SoK111-----07	3780	1860,14
E108430100000000000000026637600001	Herrenberg	71083	SoK111-----07	35985	17708,22
E108430100000000000000026907900001	Herrenberg	71083	SoK111-----07	5406	2660,29
E108430100000000000000027028000001	Herrenberg	71083	SoK111-----07	3656	1799,12
E108430100000000000000027177200001	Herrenberg	71083	SoK111-----07	33200,9	16338,17
E108430100000000000000027177200001	Herrenberg	71083	SoK112-----07	60337,1	28249,83
E108430100000000000000027344500001	Herrenberg	71083	SoK111-----07	2773	1364,59
E108430100000000000000027483700001	Herrenberg	71083	SoK111-----07	7898	3886,61
E108430100000000000000027666600001	Herrenberg	71083	SoK111-----07	5953	2929,47
E108430100000000000000028232700001	Herrenberg	71083	SoK111-----07	12098	5953,43
E108430100000000000000028242200001	Herrenberg	71083	SoK111-----07	2706	1331,62
E108430100000000000000028255000001	Herrenberg	71083	SoK111-----07	6042	2973,27
E108430100000000000000028415500001	Herrenberg	71083	SoK111-----07	6254	3077,59
E108430100000000000000028556000001	Herrenberg	71083	SoK111-----07	4670	2298,11
E108430100000000000000028600000001	Herrenberg	71083	SoK111-----08	8479	3963,93
E108430100000000000000028638400001	Herrenberg	71083	SoK111-----07	6114	3008,7
E108430100000000000000028649100001	Herrenberg	71083	SoK111-----07	6057	2980,65
E108430100000000000000028907000001	Herrenberg	71083	SoK111-----07	11215	5518,9
E108430100000000000000028986300001	Herrenberg	71083	SoK111-----07	4727	2326,16
E108430100000000000000029073400001	Herrenberg	71083	SoK111-----07	2825	1390,18
E108430100000000000000029088800001	Herrenberg	71083	SoK111-----07	6274	3087,44
E108430100000000000000029203700001	Herrenberg	71083	SoK111-----07	15441	7598,52
E108430100000000000000029302600001	Herrenberg	71083	SoK111-----08	6751	3156,09
E108430100000000000000029629200001	Herrenberg	71083	SoK111-----08	6948	3248,19
E108430100000000000000029837900001	Herrenberg	71083	SoK111-----08	5479	2561,43

E108430100000000000000030106300001	Herrenberg	71083	SoK111-----08	10725	5013,94
E108430100000000000000030171300001	Herrenberg	71083	SoK111-----08	5742	2684,39
E108430100000000000000030358000001	Herrenberg	71083	SoK111-----08	2821	1318,82
E108430100000000000000030374600001	Herrenberg	71083	SoK111-----08	10835	5065,36
E108430100000000000000030548000001	Herrenberg	71083	SoK111-----08	2908	1359,49
E108430100000000000000030664900001	Herrenberg	71083	SoK111-----08	6949	3248,66
E108430100000000000000030684100001	Herrenberg	71083	SoK111-----08	15584	7285,52
E108430100000000000000030684200001	Herrenberg	71083	SoK111-----08	6309	2949,46
E108430100000000000000030732000001	Herrenberg	71083	SoK111-----08	9338	4365,52
E108430100000000000000030874100001	Herrenberg	71083	SoK111-----08	26517	12396,7
E108430100000000000000030944100001	Herrenberg	71083	SoK111-----08	4241	1982,67
E108430100000000000000030944200001	Herrenberg	71083	SoK111-----08	3750	1753,13
E108430100000000000000030981500001	Herrenberg	71083	SoK111-----08	8446	3948,51
E108430100000000000000031344500001	Herrenberg	71083	SoK111-----08	9363	4377,2
E108430100000000000000031426000001	Herrenberg	71083	SoK111-----08	26177	12237,75
E108430100000000000000031430500001	Herrenberg	71083	SoK111-----08	12295	5747,91
E108430100000000000000031430900001	Herrenberg	71083	SoK111-----08	3770	1762,48
E108430100000000000000031433900001	Herrenberg	71083	SoK111-----08	11628	5436,09
E108430100000000000000031549500001	Herrenberg	71083	SoK111-----08	5462	2553,49
E108430100000000000000032251200001	Herrenberg	71083	SoK111-----08	6131	2866,24
E108430100000000000000032256700001	Herrenberg	71083	SoK111-----08	25387	11868,42
E108430100000000000000032491000001	Herrenberg	71083	SoK111-----08	3155	1474,96
E108430100000000000000032754600001	Herrenberg	71083	SoK111-----08	3681	1720,87
E108430100000000000000032800000001	Herrenberg	71083	SoK111-----08	14431	6746,49
E108430100000000000000032932500001	Herrenberg	71083	SoK111-----08	4132	1931,71
E108430100000000000000033004600001	Herrenberg	71083	SoK111-----08	10966	5126,61
E108430100000000000000033094100001	Herrenberg	71083	SoK111-----08	9827	4594,12
E108430100000000000000033123500001	Herrenberg	71083	SoK111-----08	21329	9971,31
E108430100000000000000033244400001	Herrenberg	71083	SoK111-----08	10006	4677,81
E108430100000000000000033422800001	Herrenberg	71083	SoK111-----08	6904	3227,62
E108430100000000000000033471500001	Herrenberg	71083	SoK111-----08	9327	4360,37
E108430100000000000000033579900001	Herrenberg	71083	SoK111-----08	34809	16273,21
E108430100000000000000033579900001	Herrenberg	71083	SoK112-----08	38290	17031,39
E108430100000000000000033749400001	Herrenberg	71083	SoK111-----08	2997	1401,1
E108430100000000000000034186100001	Herrenberg	71083	SoK111-----08	3574	1670,85
E108430100000000000000034201800001	Herrenberg	71083	SoK111-----08	6969	3258,01
E108430100000000000000034220800001	Herrenberg	71083	SoK111-----08	29944	13998,82
E108430100000000000000034245800001	Herrenberg	71083	SoK111-----08	3182	1487,59
E108430100000000000000034259300001	Herrenberg	71083	SoK111-----08	5521	2581,07
E108430100000000000000034286000001	Herrenberg	71083	SoK111-----08	18472	8635,66
E108430100000000000000034379400001	Herrenberg	71083	SoK111-----08	1826	853,66
E108430100000000000000034435300001	Herrenberg	71083	SoK111-----08	33877	15837,5
E108430100000000000000034435400001	Herrenberg	71083	SoK111-----08	1133,8	530,05
E108430100000000000000034435400001	Herrenberg	71083	SoK112-----08	31745,2	14120,26
E108430100000000000000034479100001	Herrenberg	71083	SoK114-----08	363	187,85
E108430100000000000000034507500001	Herrenberg	71083	SoK111-----08	15181	7097,12
E108430100000000000000034560800001	Herrenberg	71083	SoK111-----08	5048	2359,94
E108430100000000000000034566800001	Herrenberg	71083	SoK111-----08	7473	3493,63
E108430100000000000000034603900001	Herrenberg	71083	SoK111-----08	11408	5333,24
E108430100000000000000034868100001	Herrenberg	71083	SoK111-----08	9106	4257,06
E108430100000000000000034885800001	Herrenberg	71083	SoK111-----08	14387	6725,92

E108430100000000000000034888200001	Herrenberg	71083	SoK111-----08	9787	4575,42
E108430100000000000000035053600001	Herrenberg	71083	SoK111-----08	14598	6824,57
E108430100000000000000035393800001	Herrenberg	71083	SoK111-----08	5215	2438,01
E108430100000000000000035432400001	Herrenberg	71083	SoK111-----08	8041	3759,17
E108430100000000000000035570600001	Herrenberg	71083	SoK111-----08	6685	3125,24
E108430100000000000000035596000001	Herrenberg	71083	SoK111-----08	3711	1734,89
E108430100000000000000035605100001	Herrenberg	71083	SoK111-----08	8065	3770,39
E108430100000000000000035626300001	Herrenberg	71083	SoK111-----08	1910	892,93
E108430100000000000000035626400001	Herrenberg	71083	SoK111-----08	9590	4483,33
E108430100000000000000035669400001	Herrenberg	71083	SoK111-----08	7966	3724,11
E108430100000000000000035686000001	Herrenberg	71083	SoK111-----08	5685	2657,74
E108430100000000000000035964200001	Herrenberg	71083	SoK111-----08	12795	5981,66
E108430100000000000000035973000001	Herrenberg	71083	SoK111-----08	5105	2386,59
E108430100000000000000035992600001	Herrenberg	71083	SoK111-----08	5690	2660,08
E108430100000000000000035992800001	Herrenberg	71083	SoK111-----08	6547	3060,72
E108430100000000000000035993100001	Herrenberg	71083	SgK330-----09	9882	4250,25
E108430100000000000000036066500001	Herrenberg	71083	SoK111-----08	6429	3005,56
E108430100000000000000036540800001	Herrenberg	71083	SgK330-----09	7864	3382,31
E108430100000000000000036804400001	Herrenberg	71083	SgK330-----09	9293	3996,92
E108430100000000000000037180700001	Herrenberg	71083	SgK330-----09	6534	2810,27
E108430100000000000000037286700001	Herrenberg	71083	SgK330-----09	16694	7180,09
E108430100000000000000037537000001	Herrenberg	71083	SgK330-----09	4394	1889,86
E108430100000000000000037575100001	Herrenberg	71083	SgK330-----10	32813,36	12843,15
E108430100000000000000037575100001	Herrenberg	71083	SgK331-----10	76564,51	28504,98
E108430100000000000000037575100001	Herrenberg	71083	SgK332-----10	222562,11	78408,63
E108430100000000000000037572300001	Herrenberg	71083	SgK330-----09	8530	3668,75
E108430100000000000000037585200001	Herrenberg	71083	SgK330-----09	9459	4068,32
E108430100000000000000037617800001	Herrenberg	71083	SgK330-----09	16134	6939,23
E108430100000000000000037671200001	Herrenberg	71083	SgK330-----09	5739	2468,34
E108430100000000000000037808400001	Herrenberg	71083	SoK111-----08	1804	843,37
E108430100000000000000037813700001	Herrenberg	71083	SgK330-----09	3628	1560,4
E108430100000000000000037848800001	Herrenberg	71083	SgK330-----09	14400	6193,44
E108430100000000000000037917400001	Herrenberg	71083	SgK330-----09	10439	4489,81
E108430100000000000000037917400001	Herrenberg	71083	SgK3341-----09	1925	827,94
E108430100000000000000037917400001	Herrenberg	71083	SgK3342-----09	-1925	-346,5
E108430100000000000000038215500001	Herrenberg	71083	SgK330-----09	33669,67	14481,33
E108430100000000000000038215500001	Herrenberg	71083	SgK331-----09	66935,32	27383,24
E108430100000000000000038207100001	Herrenberg	71083	SgK330-----09	9390	4038,64
E108430100000000000000038220600001	Herrenberg	71083	SgK330-----09	14315	6156,88
E108430100000000000000038206300001	Herrenberg	71083	SgK330-----09	3808	1637,82
E108430100000000000000038206300001	Herrenberg	71083	SgK3341-----09	2643	1136,75
E108430100000000000000038206300001	Herrenberg	71083	SgK3342-----09	-2643	-475,74
E108430100000000000000038230100001	Herrenberg	71083	SgK330-----09	5239	2253,29
E108430100000000000000038317200001	Herrenberg	71083	SgK330-----09	3651	1570,3
E108430100000000000000038317200001	Herrenberg	71083	SgK3341-----09	1780	765,58
E108430100000000000000038317200001	Herrenberg	71083	SgK3342-----09	-1780	-320,4
E108430100000000000000038361100001	Herrenberg	71083	SgK330-----09	3226	1387,5
E108430100000000000000038361100001	Herrenberg	71083	SgK3341-----09	1301	559,56
E108430100000000000000038361100001	Herrenberg	71083	SgK3342-----09	-1301	-234,18
E108430100000000000000038365300001	Herrenberg	71083	SgK330-----09	9141	3931,54
E108430100000000000000038365400001	Herrenberg	71083	SgK330-----09	11119	4782,28

E108430100000000000000038394400001	Herrenberg	71083	SgK330-----09	6916	2974,57
E108430100000000000000038553900001	Herrenberg	71083	SgK330-----09	15550	6688,06
E108430100000000000000038559500001	Herrenberg	71083	SgK330-----09	4239	1823,19
E108430100000000000000038641000001	Herrenberg	71083	SgK330-----09	7331	3153,06
E108430100000000000000038641000001	Herrenberg	71083	SgK3341-----09	2110	907,51
E175940100000000000000059008900001	Herrenberg	71083	SgK1721-----MW	5267	206,63
E175940100000000000000059008900001	Herrenberg	71083	SgK330-----12	5339	1304,32
E175940100000000000000059008900001	Herrenberg	71083	SgK33410----12	1323	323,21
E175940100000000000000059008900001	Herrenberg	71083	SgK33420----12	-1323	-216,71
E175940100000000000000060003900001	Herrenberg	71083	SgK171-----0	2196	0
E175940100000000000000060003900001	Herrenberg	71083	SgK330-----12	25688,92	6275,8
E175940100000000000000060003900001	Herrenberg	71083	SgK331-----12	3682,07	855,35